

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Figure 1

Figure 2





Figure 3



Guidry + Morales
TOD 11/11/11

Top plan view of a rectangular frame assembly 100. The assembly includes a central rectangular frame 2 with a dashed outline. The frame is supported by four corner brackets 5 and 6. A central rectangular plate 44 is mounted on the frame, secured by a bolt 45. The plate 44 has a width of 13 7/16". The frame 2 has a total width of 23" and a total height of 26 1/2". The central plate 44 is positioned 31 1/2" from the left side and 4 7/8" from the top edge. The frame 2 is also 2 7/8" from the right side. The frame 2 is supported by four corner brackets 5 and 6. The frame 2 is also 2 7/8" from the right side. The frame 2 is also 2 7/8" from the right side. The frame 2 is also 2 7/8" from the right side.

Figure 4

Guidry & Morales
Bo. Thom 11.00



Figure 5






Figure 6





Figure 7

Gundry & Morales (valve outlet view)



BAFFLE DETAIL

Figure 8

Guidry & Morales
Baffle Detail